

# LIME OUT

## SCALE REMOVER



### CAUTION:

#### DANGER

THIS PRODUCT CONTAINS  
**PHOSPHORIC ACID** AND  
**GHYDROXYACETIC**.

HARMFUL IF SWALLOWED;

PROTECT EYES, SKIN, AND  
MUCOUS MEMBRANES  
FROM CONTACT WITH THIS  
PRODUCT.

CAN CAUSE BURNS.

#### FIRST AID

**EXTERNAL:**  
FLOOD SKIN WITH COOL  
RUNNING WATER FOR 15  
MINUTES

**INTERNAL:**  
DO NOT INDUCE VOMITING,  
DRINK LARGE QUANTITIES  
OF WATER FOLLOWED WITH  
MILK, MILK OF MAGNESIA,  
OR RAW EGGS.

**GET MEDICAL ATTENTION**

## SCALE REMOVER

FOR INDUSTRIAL USE ONLY

# LIME OUT

ACIDIC MATERIAL-USE WITH  
CAUTION

*Chemtron*

7361-H Lockport Place  
Lorton, VA 22079  
(703) 550-7772

KEEP OUT OF REACH OF  
CHILDREN

AVAILABLE IN:  
4/1 GALLON CASE

### DIRECTIONS FOR USE:

**CERAMIC-QUARRY TILE:**  
BRUSH SOLUTION OF 1 OUNCE  
LIME OUT TO 1 GALLON  
WATER ON SURFACE. RINSE  
WITH CLEAN WATER AND  
DRY.

**FOOD SERVING AND  
PREPARATION EQUIPMENT:**  
SCRUB SOLUTION OF 3  
OUNCES PER GALLON OF HOT  
WATER. RINSE WITH  
PORTABLE WATER AND WIPE  
DRY.

**DISHMACHINES:** USE FULL  
STRENGTH ON HARD TO  
REACH OR HEAVILY  
ENCRUSTED AREAS. ADD ½ TO  
1 GALLON TO POWDER RINSE  
TANK AND CIRCULATE UNTIL  
LIME IS REMOVED. DRAIN  
AND FLUSH WITH CLEAN HOT  
WATER.

**COFFEE URNS:** INTERIOR-  
ADD 2 GALLONS HOT WATER  
TO URN. ADD 3 OUNCES LIME  
OUT AND SWAB WITH  
SOLUTION. DRAIN AND FLUSH  
WITH HOT WATER. OUTSIDE,  
WIPE DOWN WITH 1 OUNCE TO  
3 GALLON HOT WATER USING  
SPONGE AND RINSE WITH  
CLEAR WATER.

**STEAM TABLES:** FILL WITH  
SOLUTION OF 1 OUNCE OER  
GALLON OF HOT WATER.  
HEAT SOLUTION AT  
OPERATING TEMPERATURE  
FOR 15 MINUTES. DRAIN AND  
RINSE THOROUGHLY.

**STAINLESS STEEL:** APPLY  
FULL STRENGTH WITH CLOTH.

*Chemistry And Technology For A Cleaner World*